



Painting Report

Responsible: QM
QA-8.06.2

INSPECTOR	Mathias Kristensen
CLIENT	Seaway 7
OBJECT/DRWG. NO.	
ITEM REF	427666-01. 427677-01
PAINTING SPEC	

Images


Painting Report

Responsible: QM
QA-8.06.2





Painting Report

Responsible: QM
QA-8.06.2

Painting Report

Responsible: QM
QA-8.06.2



Control of Surface Before Pretreatment					Approved
Oil & Grease					☒
Grinding		R=2			☒
Weld Splatters					☒
Rust Degree	☐ A	☒ B	☐ C	☐ D	☒

Pretreatment				Approved
☐ SA3	☒ SA2.5	☐ SA2	☐ SA1	☒
☐ ST3	☐ ST2	☐ ST1		☐
Chloride Contamination Test			14 mg/m ²	☒
Solvent Cleaning				☒

Painting Report

Responsible: QM
QA-8.06.2

Surface Profile ISO Comparator Test ISO 8503-1	☐ (G) Fine	☒ (G) Medium	☐ (G) Coarse	☒
Final Control Visual				☒
Adhesion Test				☐

Date / Time	Location	Layer	RH %	Air Temp	Steel Temp. A	DEW PKT:BB	DIFF. A-B	Remarks
29-Nov-2025 16:58	B hall		49.1	19.4	19.2	8.5	10.7	

Additional Information			
Object/DRWG. No.		Test Equipment	PosiTector Advanced 6000
DPM Probe	1055734	FRNS Probe	1051796
SST Probe	1057515		
Additional Information notes			

Approval Section	
APPROVAL DATE	29-Nov-2025
INSPECTOR	Frosio Level III Senior Inspector
CERT NO	9400
SIGNATURE	
Alex Heine Kristensen 	

Painting Report

Responsible: QM
QA-8.06.2

3rd Party Approval

Inspector Name	Company Name	Date	Time	Signature
NKF	Seaway 7	29-Nov-2025	16:50	
Inspection Notes				