

Painting Report

Responsible: QM
QA-8.06.2

INSPECTOR	Micklas Skov Skelmose
CLIENT	test
OBJECT/DRWG. NO.	123
ITEM REF	
PAINTING SPEC	

Images

Control of Surface Before Pretreatment					Approved
Oil & Grease					☒
Grinding		R=2			☒
Weld Splatters					☒
Rust Degree	☐ A	☒ B	☐ C	☐ D	☒

Pretreatment				Approved
☐ SA3	☒ SA2.5	☐ SA2	☐ SA1	☒
☐ ST3	☐ ST2	☐ ST1		☐
Chloride Contamination Test			mg/m ²	☐
Solvent Cleaning				☐
Surface Profile ISO Comparator Test ISO 8503-1	☐ (G) Fine	☒ (G) Medium	☐ (G) Coarse	☒
Final Control Visual				☒
Adhesion Test				☐

Painting Report

Responsible: QM
QA-8.06.2

Paint Supplier		HEMPEL	
Coat/Thinner	Type Used	Komp. A	Komp. B

Coat No.	DFT No.	Batch No.	Min. Measured Film Thk.	Max Measured Film thk.	Average Film Thk.
----------	---------	-----------	-------------------------	------------------------	-------------------

Date / Time	Location	Layer	RH %	Air Temp	Steel Temp. A	DEW PKT:BB	DIFF. A-B	Remarks
-------------	----------	-------	------	----------	---------------	------------	-----------	---------

Additional Information			
Object/DRWG. No.	123	Test Equipment	PosiTector Advanced 6000
DPM Probe	1055734	FRNS Probe	1051796
SST Probe	1057515		
Additional Information notes			

Approval Section

APPROVAL DATE	08-Dec-2025
INSPECTOR	Frosio Level III Senior Inspector
CERT NO	9400
SIGNATURE	
Alex Heine Kristensen 	